




Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
Historic name(s): **Commercial Building, Not Named**
Common name: _____
Location: **06th St., 2000**

Description

See PELA Survey #S19.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: 1945 ca. Alteration Date: _____
PELA #S19.

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: _____
NR Listing Name: _____
Consultant Recommend.: _____
NR District Ref. Number: _____ Contributing Status: _____
Discussion: _____
Notes: _____

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____





Tuscaloosa
 Greater Downtown Study
 Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
 Historic name(s): **Commercial Building, Not Named**
 Common name: _____
 Location: **06th St., 2123**

Description

Demolished prior to 2006.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
 Historic Use: _____ Current Use: _____
 Function: _____ Function: _____

Historical Information

Construction Date: _____ Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
 NR Listing Name: Downtown Tuscaloosa Historic District
 Consultant Recommend.: _____
 NR District Ref. Number: 65 Contributing Status: contributing
 Discussion: _____
 Notes:

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
 Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____




Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone _____
Historic name(s): **Commercial Building, Not Named**
Common name: _____
Location: **06th St., 2123**

Description

PELA Survey #S36



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: _____ Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: _____
NR Listing Name: _____
Consultant Recommend.: _____
NR District Ref. Number: _____ Contributing Status: _____
Discussion: _____
Notes: _____

Documentation

Photos: Photo View of: Date Surveyed: _____ Modified: 4/6/2009
 prints _____ Surveyor: David B. Schneider
 slides _____
 negatives _____
 digital _____






Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
 Historic name(s): **Commercial Building, Not Named**
 Common name: _____
 Location: **06th St., 2301**

Description

Resource was demolished prior to 2006. See Downtown Tuscaloosa Historic District National Register nomination, resource #72.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
 Historic Use: _____ Current Use: _____
 Function: _____ Function: _____

Historical Information

Construction Date: 1898 _____ Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
 NR Listing Name: Downtown Tuscaloosa Historic District
 Consultant Recommend.: _____
 NR District Ref. Number: 72 Contributing Status: noncontributing
 Discussion: _____
 Notes: _____

Documentation

Photos:	Photo	View of:	Date Surveyed: <u>6/10/2006</u>	Modified: <u>4/6/2009</u>
<input type="checkbox"/> prints	_____	_____	Surveyor: <u>David B. Schneider</u>	_____
<input type="checkbox"/> slides	_____	_____		
<input type="checkbox"/> negatives	_____	_____		
<input type="checkbox"/> digital	_____	_____		




Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
Historic name(s): **Commercial Building, Not Named**
Common name: _____
Location: **06th St., 2305-2307**

Description

Resource was demolished prior to 2006. See Downtown Tuscaloosa Historic District National Register nomination, resource #73.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: 1910 ca. Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
NR Listing Name: Downtown Tuscaloosa Historic District
Consultant Recommend.: _____
NR District Ref. Number: 73 Contributing Status: _____
Discussion: D055
Notes: _____

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____






Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
Historic name(s): **Commercial Building, Not Named**
Common name: _____
Location: **06th St., 2309-2311**

Description

Resource was demolished prior to 2006. See Downtown Tuscaloosa Historic District National Register nomination, resource #75.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: 1910 ca. Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
NR Listing Name: Downtown Tuscaloosa Historic District
Consultant Recommend.: _____
NR District Ref. Number: 75 Contributing Status: noncontributing
Discussion: _____
Notes: _____

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____






Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
Historic name(s): **Commercial Building, Not Named**
Common name: _____
Location: **06th St., 2315**

Description

Resource was demolished prior to 2006. See Downtown Tuscaloosa Historic District National Register nomination, resource #77.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: 1910 ca. Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
NR Listing Name: Downtown Tuscaloosa Historic District
Consultant Recommend.: _____
NR District Ref. Number: 77 Contributing Status: noncontributing
Discussion: _____
Notes: _____

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____






Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
Historic name(s): **Commercial Building, Not Named**
Common name: _____
Location: **06th St., 2317**

Description

Resource was demolished prior to 2006. See Downtown Tuscaloosa Historic District National Register nomination, resource #78.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: _____ Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
NR Listing Name: Downtown Tuscaloosa Historic District
Consultant Recommend.: _____
NR District Ref. Number: 78 Contributing Status: noncontributing
Discussion: _____
Notes: _____

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____






Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
Historic name(s): **Commercial Building, Not Named**
Common name: _____
Location: **06th St., 2319-2323**

Description

Resource was demolished prior to 2006. See Downtown Tuscaloosa Historic District National Register nomination, resource #79.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: 1910 ca. Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
NR Listing Name: Downtown Tuscaloosa Historic District
Consultant Recommend.: _____
NR District Ref. Number: 79 Contributing Status: noncontributing
Discussion: _____
Notes: _____

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____





Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone _____


Historic name(s): **Commercial Building, Not Named**

Common name: _____

Location: **07th St., 2223 - 2225**

Description

See PELA Survey #S52



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: 1933 ca. Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: _____

NR Listing Name: _____

Consultant Recommend.: _____

NR District Ref. Number: _____ Contributing Status: _____

Discussion: _____

Notes:

Documentation

Photos:	Photo	View of:
<input type="checkbox"/> prints	_____	_____
<input type="checkbox"/> slides	_____	_____
<input type="checkbox"/> negatives	_____	_____
<input type="checkbox"/> digital	_____	_____

Date Surveyed: 6/10/2006 Modified: 4/6/2009

Surveyor: David B. Schneider






Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone _____
 Historic name(s): **Commercial Building, Not Named**
 Common name: _____
 Location: **07th St., 2231**

Description

See PELA Survey #S51.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
 Historic Use: _____ Current Use: _____
 Function: _____ Function: _____

Historical Information

Construction Date: 1957 ca. Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: _____
 NR Listing Name: _____
 Consultant Recommend.: _____
 NR District Ref. Number: _____ Contributing Status: _____
 Discussion: _____
 Notes: _____

Documentation

Photos:	Photo	View of:	Date Surveyed: 6/10/2006	Modified: 4/6/2009
<input type="checkbox"/> prints	_____	_____	Surveyor: David B. Schneider	_____
<input type="checkbox"/> slides	_____	_____		
<input type="checkbox"/> negatives	_____	_____		
<input type="checkbox"/> digital	_____	_____		




Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
Historic name(s): **Commercial Building, Not Named**
Common name: Ward Bld.
Location: **07th St., 2317-23198**

Description

Resource was demolished prior to 2006. See Downtown Tuscaloosa Historic District National Register nomination, resource #84.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: 1916 _____ Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
NR Listing Name: Downtown Tuscaloosa Historic District
Consultant Recommend.: _____
NR District Ref. Number: 84 Contributing Status: noncontributing
Discussion: _____
Notes:

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____




Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
Historic name(s): **Commercial Building, Not Named**
Common name: _____
Location: **07th St., 2516**

Description

Subject building was demolished after the Tuscaloosa Downtown Historic District Expansion was listed in the NR; See Downtown Tuscaloosa Historic District National Register nomination, resource #89.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: _____ Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
NR Listing Name: Downtown Tuscaloosa Historic District
Consultant Recommend.: _____
NR District Ref. Number: 89 Contributing Status: noncontributing
Discussion: _____
Notes: _____

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____






Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone _____
 Historic name(s): **Commercial Building, Not Named**
 Common name: _____
 Location: **21st Ave., 617**

Description

See PELA Survey #S50.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
 Historic Use: _____ Current Use: _____
 Function: _____ Function: _____

Historical Information

Construction Date: _____ Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: _____
 NR Listing Name: _____
 Consultant Recommend.: _____
 NR District Ref. Number: _____ Contributing Status: _____
 Discussion: _____
 Notes: _____

Documentation

Photos:	Photo	View of:	Date Surveyed: _____	Modified: <u>4/6/2009</u>
<input type="checkbox"/> prints	_____	_____	Surveyor: <u>David B. Schneider</u>	_____
<input type="checkbox"/> slides	_____	_____	_____	_____
<input type="checkbox"/> negatives	_____	_____	_____	_____
<input type="checkbox"/> digital	_____	_____	_____	_____




Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone _____
 Historic name(s): **Commercial Building, Not Named**
 Common name: _____
 Location: **22nd Ave., 718 - 726**

Description

See PELA Survey #S59



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
 Historic Use: _____ Current Use: _____
 Function: _____ Function: _____

Historical Information

Construction Date: 1933 ca. Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: _____
 NR Listing Name: _____
 Consultant Recommend.: _____
 NR District Ref. Number: _____ Contributing Status: _____
 Discussion: _____
 Notes: _____

Documentation

Photos:	Photo	View of:	Date Surveyed: 6/10/2006	Modified: 4/6/2009
<input type="checkbox"/> prints	_____	_____	Surveyor: David B. Schneider	_____
<input type="checkbox"/> slides	_____	_____		
<input type="checkbox"/> negatives	_____	_____		
<input type="checkbox"/> digital	_____	_____		






Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
Historic name(s): **Commercial Building, Not Named**
Common name: _____
Location: **23rd Ave., 525-531**

Description

Resource was demolished prior to 2006. See Downtown Tuscaloosa Historic District National Register nomination, resource #94; PELA Survey #S7.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: 1922 ca. Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
NR Listing Name: Downtown Tuscaloosa Historic District
Consultant Recommend.: _____
NR District Ref. Number: 94 Contributing Status: noncontributing
Discussion: _____
Notes:

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____






Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
 Historic name(s): **Commercial Building, Not Named**
 Common name: _____
 Location: **23nd Ave., 612**

Description

Resource was demolished prior to 2006. See Downtown Tuscaloosa Historic District National Register nomination, resource #96.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
 Historic Use: _____ Current Use: _____
 Function: _____ Function: _____

Historical Information

Construction Date: 1921 _____ Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: 5/15/1986; rev. 1989,1997
 NR Listing Name: Downtown Tuscaloosa Historic District
 Consultant Recommend.: _____
 NR District Ref. Number: 96 Contributing Status: noncontributing
 Discussion: _____
 Notes:

Documentation

Photos:	Photo	View of:	Date Surveyed: <u>6/10/2006</u>	Modified: <u>4/6/2009</u>
<input type="checkbox"/> prints	_____	_____	Surveyor: <u>David B. Schneider</u>	
<input type="checkbox"/> slides	_____	_____		
<input type="checkbox"/> negatives	_____	_____		
<input type="checkbox"/> digital	_____	_____		




Tuscaloosa
 Greater Downtown Study
 Historic Resource Survey - 2006

Survey Number: _____ Gone _____
 Historic name(s): **Van Hoose Building**
 Common name: _____
 Location: **23rd Ave., 705**

Description

See PELA Survey #S67



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
 Historic Use: _____ Current Use: _____
 Function: _____ Function: _____

Historical Information

Construction Date: 1933 ca. Alteration Date: _____

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: _____
 NR Listing Name: _____
 Consultant Recommend.: _____
 NR District Ref. Number: _____ Contributing Status: _____
 Discussion: _____
 Notes: _____

Documentation

Photos:	Photo	View of:	Date Surveyed: 6/10/2006	Modified: 4/6/2009
<input type="checkbox"/> prints	_____	_____	Surveyor: David B. Schneider	_____
<input type="checkbox"/> slides	_____	_____		
<input type="checkbox"/> negatives	_____	_____		
<input type="checkbox"/> digital	_____	_____		






Tuscaloosa

Greater Downtown Study
Historic Resource Survey - 2006

Survey Number: _____ Gone - _____
Historic name(s): **Commercial Building, Not Named**
Common name: _____
Location: **University Blvd., 2009**

Description

See PELA Survey #S17.



Condition: _____ Integrity: _____ Ownership: _____ Category: _____
Historic Use: _____ Current Use: _____
Function: _____ Function: _____

Historical Information

Construction Date: 1965 ca. Alteration Date: _____
PELA #S17.

Evaluation

National Register Status: N/A Individually Listed Listed in District Date: _____
NR Listing Name: _____
Consultant Recommend.: _____
NR District Ref. Number: _____ Contributing Status: _____
Discussion: _____
Notes: _____

Documentation

Photos: Photo View of: Date Surveyed: 6/10/2006 Modified: 4/6/2009
Surveyor: David B. Schneider
 prints _____
 slides _____
 negatives _____
 digital _____

